

Oil Field Environmental Incident Summary

Incident: 20140215213803 **Date/Time of Notice:** 02/15/2014 20:14

Responsible Party: C12 Energy

Well Operator: C12 ENERGY: NORTH DAKOTA LLC

Well Name: DICKINSON-HEATH-SAND UNIT 06

Field Name: DICKINSON

Well File #: 4831

Date Incident: 2/15/2014

Time Incident: 14:00

Facility ID Number:

County: STARK

Twp: 140

Rng: 96

Sec: 22

Qtr: SW NW

Location Description: Spill is to the southwest of well 6s location coming from the flowline. Spill is in a hay field.

Submitted By: Owen Ryan

Received By:

Contact Person: Owen Ryan
2054 UNIVERSITY AVENUE
SUITE 400
BERKELEY, CA 94794

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building: 800 Feet

Distance Nearest Water Well: 1 Miles

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.2	barrels	0	barrels		
Brine	1.8	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 12/16/2014

Clean Up Concluded: 8/28/2014

Risk Evaluation:

None

Areal Extent:

40 ft^2

Potential Environmental Impacts:

Soil in the small area is contaminated. Will remove shortly.

Action Taken or Planned:

All wells going to that flow line were shut in. We will be cleaning up when we can get crews.

Wastes Disposal Location: Chimney Butte Landfill in Fairfield, ND

Agencies Involved:

Updates

Date: 2/17/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from an off-location pipeline leak in a hay field. Followup is necessary.

Date: 2/25/2014 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 2/15/2014.

Site has been cleaned up, with only newly disturbed ground visible. It was recommended to the company man to re-seed the impacted area.

No followup is necessary at this time.